

Attorney Docket No. 1793.1085

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

re Patent Application of:

Byung-youn SONG et al.

Application No.: 10/706,949

**ATTENTION** 

Confirmation No.: 7769

CERTIFICATE OF CORRECTION

Filed: November 14, 2003

**BRANCH** 

U.S. Patent No.: 7,458,087

Issued: November 25, 2008

OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

For:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: F.W. 3. 7009

By:

Gerie M. Garner, fl Registration No. 34,172

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500

Facsimile: (202) 434-1501

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## CERTIFICATE OF CORRECTION

PATENT NO: 7,458,087

DATED: November 25, 2008

INVENTOR(S): Byung-youn SONG et al.

First Page, Column 2 (U.S. Patent Documents), Line 9, change "Mori et al" to --Mori et al.--.

First Page, Column 2 (Foreign Patent Documents), Line 2, change "9/1996" to --8/1996--

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 7,458,087

No. of add'l copies @ 50¢ per page